

## Task Specific Risk Assessment – RA022

<b>BUSINESS UNIT: BIO-RECYCLING</b>		DATE OF ASSESSMENT: 22/06/08	DATE TO BE REVIEWED: JUNE 2010
<b>WORK ACTIVITY:</b> DOMESTIC WASTE DISPOSAL BY TANKERS		ASSESSMENT CARRIED OUT BY: John Eley	
<b>LOCATION OF WORK ACTIVITY:</b> ANY TW DOMESTIC WASTE RECEPTION SITE		FINDINGS OF ASSESSMENT COMMUNICATED TO:	
<b>ARE ALL REQUIRED CONTROLS IN PLACE PRIOR TO WORK ACTIVITY COMMENCING? (IF NO STATE WHY NOT)</b> YES		SUPERVISOR/TEAM LEADER: Mark Lewington	
Hazards Identified	People at Risk	Precautions in Place	Additional Control Measures Required
Fall/Slip/Trip	Vehicle Driver	A minor risk. The driver may fall when alighting his cab. There are no practical precautions that can be put in place.	None
Noise	Vehicle Driver Passers-by		None. Noise levels and exposure times are low.
Gas	Vehicle Driver Passers-by	There is a minor risk of exposure to sewage gases if the vehicle tank vents. Gases will be diluted by atmosphere.	None. Veh. tanks do not vent out during disposal. Any gases are diluted by the atmosphere
Exposure to sewage	Vehicle Driver	A medium risk of sewage splash when coupling/uncoupling the discharge hose.	Personal hygiene leaflet distributed to all customers.
Moving vehicles	Vehicle Driver	Drivers must be in possession of the appropriate driving licences. Site speed limits in place. Reminders sent to all customers.	None

Level of risk with current precautions in place (circle one) : L M H

Residual risk with additional controls in place (circle one) : L M H